

**FAG Service Info** 

## 803750.10.H195

## Supplied ABS ring must be used

Manufacturer: Bova MAN Mercedes-Benz Neoplan Scania Setra Volvo

Part no.: 803750.10.H195 (Repair Insert Unit)

See parts catalogue for current as signment



Im age 1: The original cassette rotary shaft seal (left) must not be re-used. Instead, the ABS ring (right) supplied with the Repair Insert Unit (RIU) must be installed.

In most cases, an insert unit is installed ex works for the vehicle or axle m anufacturers listed above. FAG offers the Repair Insert Unit (RIU), part number 803750.10.H195, as a repair solution.

The RIU is a pre-assem bled, pre-greased and sealed unit. No additional seals are required. This enables faster and easier installation. A suitable, model-specific ABS ring is supplied by Schaeffler Automotive Aftermarket. The dimensions of this ABS ring are different from the originally installed ABS cassette rotary shaft seal.

The supplied ABS ring m ust be used when installing the RIU. The original cassette rotary shaft seal must not be re-used.





Image 2: Insert Unit

Image 3: Package content of the Repair Insert Unit (RIU) incl. ABS ring

You want more? We can help!

Phone: +44 (0) 1432 264 264 Fax: +44 (0) 1432 375 760 afterm arket.uk@ schaeff ler.com www.repxpert.co.uk

