



## FAG Service Info



# Installation instructions for FAG 201050 / 632203.H195

## Check the protective rings behind the wheel hub

Manufacturer: Mercedes-Benz

Models: Actros M P2 / M  
P3 Antos  
Atego / Atego 2 / Atego 3  
Axor / Axor 2

Part no.: 201050 (wheel bearing)  
632203.H195 (TAM- Truck Axle Modul)

See parts catalogue for current assignment



Image 1: FAG wheel bearing unit (TAM) – part no.: 632203.H195 (left), FAG wheel bearing – part no.: 201050 (right)

Schaeffler Automotive Aftermarket offers both the individual wheel bearing and the complete wheel bearing unit (TAM) for the vehicles listed above. This consists of a wheel bearing housing, wheel bearing and ABS sensor ring.

If it is found during the repair that the protective ring behind the wheel hub is defective, the protective ring must be replaced. One way of ordering a replacement is based on the vehicle manufacturer.

When identifying the part, please note that there are three different variants. To identify the correct protective ring, the diameter of the sealing seat must be measured.

Measured diameter	Protective ring required	OE-Part no.
86,70 to 86,85 mm	with no coloured marking	A 970 997 03 46
86,85 to 87,05 mm	with red marking	A 970 997 09 46
87,05 to 87,30 mm	with white marking	A 970 997 10 46



Figure 2: To determine which of the three protective rings needs to be installed, the diameter of the sealing seat must be measured



Image 3: The protective rings have different inner diameters.

Please observe the vehicle manufacturer specifications!

### You want more? We can help!

Phone: +44 (0) 1432 264  
264 Fax: +44 (0) 1432 375  
760 aftermarket.uk@  
schaeffler.com  
www.repxpert.co.uk

SCHAEFFLER  
REPXPERT