


# WINNARD

## PRODUCT AWARENESS SUSPECTED CRACKED BRAKE DISCS ?

This issue mainly affects the flat design brake discs such as our part numbers:  
DA1058, DA1058S, DA1059, DA1063, SAU1030, SAU1031,  
VO1071(K), VO1072(K), VO1077(K), VO1078(K), VO1079(K)  
& VO1083(K).

Care should be taken when opening these boxes and consideration made if the braking surface is marked by a sharp blade.

Any scoring caused by a blade is not detrimental to the discs operation and will be worn away during normal use.



### SCORE LINE CAUSE BY OPENING THE BOX WITH A SHARP BLADE

