

WINNARD


TECHNICAL BULLETIN

SCANIA BRAKE DRUM SC1021 DESIGN CHANGE

Original Equipment Part Numbers: 1361331, 1414153, 2109552, 2378715, 324878, 360571, 368269, 392386


WHAT HAS CHANGED ?

The three M12x1.75 threaded holes used to remove the brake drum from the hub have changed position.



OLD DRILLING POSITION


SC1021
DRILLING PLAN VIEW



NEW DRILLING POSITION


WHY HAS IT CHANGED ?

New hub design means that the central threaded holes would NOT engage with the hub when being removed.



OLD HUB

SCANIA HUB DESIGN
ILLUSTRATION



NEW HUB