


WINNARD

TECHNICAL BULLETIN HUBKIT INSTALLATION OBSERVATION




When installing HUBKITS it is vital **not** to damage or dislodge the central retaining clip in the bearing.

Due to the weight of the part, care should be taken to ensure the HUBKIT slides onto the stub axle without catching the central retaining clip.

Placing excessive load on one side of the bearing can also dislodge the clip. Any movement or damage to this clip can cause operational failure.

Example bearing assembly



A dislodged clip can be re-fitted, but you **MUST** ensure the clip is seated correctly and holding both bearings flush.

If in doubt contact our technical department for guidance.

To help reduce the possibility of damaging the clip we recommend that heavy handling equipment is used or a two man lift system adopted.

